POTERNATOR INTERORIC STUDY

Block

Lot

Address

B-2660

220

16, 16A, 16B 836-(840) Hollins Street

MAG1#0426605711

Approximate age

1800-1845

1845-1860

1865-1880

1880-1896

1896-on

Rating Architectural		Condition			
A	Significant-save	good	fair	poor	bad
В	Quality-Indiv./groups-save	good	fair	poor	bad
C	Important to street/groups	good	fair	poor	bad
(D)	Insignificant/detrimental	good	fair	poor	bad


Notable features:

This was the site of Ross Winans' house, torn down after 1896. His business was across Baltimore Street (Sachse air view).

The ugly Penn Motor Co. structure (840) is built on the rear lot 1K which fronts on Baltimore Street. The long one-story brick building at 836 is a delivery company garage and warehouse, the western-most 51'6" of which are an open truck yard.

Environmental context:

Rating is "detrimental" because of varied uses of land -damages Baltimore Street and the 800 block of Hollins Street
and St. Peter's on Poppleton Street. Chain link fences,
warehouse and worse construction and mostly open truck storage
(Continued on next sheet)



FOPPLETON HISTORIC STUDY (Continuation page) B-2660

Block

ho t

Address

2:11

16, 16A,


836-(840) Holling Street


16 15

Environmental context (continued):


yards is the view that the very nice houses on the south side of Hollins have to look at here.

If it is economically feasible, housing should be built here; but if not, the present users should improve their lots with landscape treatment including walls. It is also regrettable that the terminating north view up Parkin Street is a bunch of trucks behind a 10' chain link fence.





B-2660 836 Hollins Street Sanborn Maps



Demolished

B-2660 836 Hollins Street Block 220 Lot 016a Baltimore City Baltimore West Quad.

